## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L7	10	(wavelength with degradation with compar \$6) and (laser with (tun \$6 or adjst\$6))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/10 23:27
L8	2392	((702/8) or (702/40) or (702/49) or (702/57) or (702/60) or (702/64)). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/03/11 01:06
L9	0	L8 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and (compar \$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/11 01:06
L10	4288	((702/65) or (702/75) or (702/79) or (702/80) or (702/107) or (702/179) or (702/182)).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/03/11 01:06
L11	0	L10 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and (compar \$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/11 01:06
L12	2981	((702/183) or (702/184) or (702/189)).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/03/11 01:06
L13	0	L12 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and (compar \$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	000	2008/03/11 01:06
L14	2616	((372/20) or (372/29.01) or (374/183)).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/03/11 01:07
L15	5	L14 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and (compar \$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	000	2008/03/11 01:07
S1	2	("20030026302").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/07/17 15:08

S2	3114	(measur\$6 with (degradation or wear\$6)) and diode\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/17 15:11
S3	1500	S2 and laser	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/17 15:12
S4	96	S3 and (bragg or "DBR")	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/17 15:54
S5	41	S4 and tunable	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/17 15:54
S6	31	S5 and (compens\$6 or calibrat\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/17 15:56
S7	8	S6 and "gain"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/17 17:15
S8	13	(measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and "gain" and (compar\$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/17 19:00
S9	1	(jeffrey and west).xa. and extinction.ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/17 19:01
S10	20	("20020027690"   "20020141515"   "20020161737"   "20020161737"   "4200861"   "4864649"   "4998111"   "5502298"   "5535038"   "5617237"   "5850409"   "5974063"   "6014235"   "6101213"   "6115113"   "6256329"   "6292497"   "6314393"   "6414974"   "6477275"	US-PGPUB; USPAT; USOCR	OR	OFF	2007/07/17 19:16
S11	4	S10 and wavelength	US-PGPUB; USPAT; USOCR	OR	OFF	2007/07/17 20:59
S12	1	("6993459").URPN.	USPAT	OR	OFF	2007/07/17 19:17
S13	1994	(transition with wavelength) and (laser near5 diode\$1)	US-PGPUB; USPAT; USOCR	OR	ON	2007/07/17 21:13
S14	21	S13 and degradation and (current with (point\$1 or node\$1))	US-PGPUB; USPAT; USOCR	OR	ON	2007/07/17 21:10

S15	21	S14 and diode	US-PGPUB; USPAT; USOCR	OR	ON	2007/07/17 21:10
S16	2	(transition with wavelength) and (laser and diode\$1) and degradation and (current with (point\$1 or node\$1) with wavelength)	US-PGPUB; USPAT; USOCR	OR	ON	2007/07/17 21:21
S17	39	(laser and diode\$1) and degradation and (current with (point\$1 or node\$1) with wavelength)	US-PGPUB; USPAT; USOCR	OR	ON	2007/07/18 18:58
S18	2	("20060129344").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/07/18 18:58
S19	2209	((702/8) or (702/40) or (702/49) or (702/57) or (702/60) or (702/64)). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/07/19 14:20
S20	0	\$19 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and (compar \$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	MON MANAGEMENT	2007/07/19 14:25
S21	3847	((702/65) or (702/75) or (702/79) or (702/80) or (702/107) or (702/179) or (702/182)).OQLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/07/19 14:24
S22	0	\$21 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and (compar \$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/19 14:27
S23	2544	((702/183) or (702/184) or (702/189)).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/07/19 14:26
S24	0	\$23 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and (compar \$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2007/07/19 14:29
<b>S</b> 25	2565	((372/20) or (372/29.01) or (374/183)).OOLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2007/07/19 14:28

S26	5	\$25 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and (compar \$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR		2007/07/19 14:29
S27	13	(measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and "gain" and (compar\$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 17:03
S28	145	(gain near5 current\$1) and ((measur\$6 or determin\$6 or calculat \$6) with (power or ealon or wavelength)) and (compar\$6 with (degrad \$6 or wear\$6))	US-PGPUB; USPAT; EPO; JPO; DERWENT	STOOR	ON	2008/03/06 17:22
S29	1	\$27 and ((set\$6 or select \$6 or choos\$6) near5 gain\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 17:25
\$30	2390	((702/8) or (702/40) or (702/49) or (702/57) or (702/60) or (702/64)). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/03/06 17:26
S31	0	S30 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and "gain" and (compar\$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 17:27
S32	4284	((702/65) or (702/75) or (702/79) or (702/80) or (702/107) or (702/179) or (702/182)).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/03/06 17:28
<b>S3</b> 3	0	S32 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and "gain" and (compar\$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 17:28
S34	2973	((702/183) or (702/184) or (702/189)).OCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/03/06 17:28

\$35	0	\$34 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and "gain" and (compar\$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 17:28
S36	2616	((372/20) or (372/29.01) or (374/183)).COLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/03/06 17:29
S37	5	\$36 and (measur\$6 with degradation with laser) and compensat\$6 and wavelength and (current with laser) and "gain" and (compar\$6 with measur\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR		2008/03/06 17:29
S38	0	\$37 and ((set\$6 or select \$6 or choos\$6) near5 gain\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 17:32
<b>S3</b> 9	145	(gain near5 current\$1) and ((measur\$6 or determin\$6 or calculat \$6) with (power or etalon or wavelength)) and (compar\$6 with (degrad\$6 or wear\$6))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 21:09
S40	94	S39 and ((set\$6 or select \$6 or choos\$6) near5 gain\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 21:10
S41	27	S40 and laser	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 21:14
S42	8	(gain near5 current\$1) and ((measur\$6 or determin\$6 or calculat \$6) with (voltage or power or etalon or wavelength)) and (compar\$6 with (degrad \$6 or wear\$6)) and ((set \$6 or select\$6 or choos \$6) near5 gain\$1) and laser and (current near5 set\$6)	US-PCPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2008/03/06 21:23

<sup>3/11/08 1:07:54</sup> AM

C:\ Documents and Settings\ mcharioui\ My Documents\ EAST\ Workspaces\ 10533349.wsp